

Activities > 206873

Project

HammondCare Greenwich Redevelopment Main Works

Date Opened

09/10/2026

Activity Type

Regulatory Visit

Date Closed

09/10/2026

Number of

1

Senior Managers Involved

Michael Awad

Mark Reynolds

Impact

Environment

Status

OK

Number of Workers

5

Assigned To

Jack Isemonger

Hours spent per worker

3

Completed By

Jack Isemonger

Total Hours

15

Details

SafeWork NSW Regulatory Visit – 09/10/2026

SafeWork NSW Inspector ZD attended site at approximately 1130hrs in response to a community complaint regarding dust management.

Jack Isemonger encountered the Inspector outside Gate 2 whilst undertaking a safety walk. The Inspector was conducting an independent inspection and noted water misting providing coverage to the external footpath, with mist drifting across the road. Also witnessed the road sweeper operating onsite and a worker using a hose for dust suppression at Gate H2.

Inspector attended the site office at approximately 1145hrs, where the following documentation and controls were reviewed:

Site management plans, dust controls and monitoring arrangements.

Hindmarsh Environmental Management Plan and relevant insurances.

Hindmarsh Silica SWMS and SWMS review checklist.

Chalouhi SWMS, SWMS review checklist, Civil HRCW SWMS and silica risk assessment.

SiteHive dust monitoring, including third-party review by Acoustic Logic.

Inspector confirmed satisfaction with the documentation and requested a guided site inspection,

commencing at approximately 1300hrs.

During the inspection, the following controls were observed and photographed by the Inspector:

Six operational blowers positioned around site.

Three workers undertaking dust suppression using hoses.

SiteHive dust monitoring stations.

Site movement board, including planning for forecast wind conditions and directional changes.

Inspection Outcome

Inspector ZD complimented the site on its planning and implementation of dust management controls, noting that appropriate risk controls were in place and being implemented effectively.

Inspector advised they were satisfied with the site's compliance and management of dust-related risks.

No further action required and no notices issued.
